

Manual

Software SPECTRO-T-3-DOCAL-Scope V1.0

(PC software for Microsoft® Windows® 10)

for sensors of SPECTRO-T-3 Series

This manual describes the installation of the PC software SPECTRO-T-3-DOCAL-Scope.

The software was developed for calibrating sensors of the SPECTRO-T-3 Series. Here, calibration takes place with a calibration wizard, which guides the user step by step through the calibration process via the corresponding instruction windows.

The calibration can optionally be done with NIR plates whose N^{*}i^{*}r^{*} values are available in a file. During the calibration you will be asked to load this file. Then a NIR plate is placed in front of the sensor. The corresponding N^{*}i^{*}r^{*} values are then loaded from the file by entering the corresponding serial number.

There are 3 preconditions

1. You need **one** reference plate. This is available from the supplier of the sensor.
2. You need different NIR plates. These are available from the supplier of the sensor.
3. You need a file (.ini file) in which the N^{*}i^{*}r^{*} values for the various NIR plates are stored. This file is also available from the supplier (via download → NIR plate Data Files).

Another method is to enter the N^{*}i^{*}r^{*} values manually. In this case you also need a reference surface and different surfaces from which the N^{*}i^{*}r^{*} values are known.

If the calibration values are saved to a file after successful calibration, they can be loaded as a calibration template for the next calibration, expanded, or sent directly to the sensor.

After successful calibration, the sensor can be taught different surfaces.

The parameters required for this are enabled on the PC interface. Other parameters, which can only be set via the respective main software, or which were permanently set during calibration, are only displayed in gray and cannot be changed.

As usual, the sensor data are visualized on the PC surface.

The current space coordinates N^{*}i^{*}r^{*} as well as their difference (delta N^{*}, delta i^{*}, delta r^{*}) to a respective hit are also displayed.

The space coordinates as well as their deltas and two freely adjustable documentation entries can then be output to a label printer, for example. The data can also be saved in a file which can then be reloaded for viewing.

We recommend the following label printer and accessories:

Printer	Accessories	Accessories
Company: cab Produkttechnik GmbH & Co. KG Model: cab EOS2/300 Item No. 5978202	Adhesive roll label Item No. 5780036 Material: TF Satin White Width x Height: 50x30mm	Thermal transfer ribbon Item No. 5556661

You can download drivers, documentation, additional software, etc. at the following link:

https://www.cab.de/en/marketing/label-printer/eos25/?ref=nav_lang

The installation of the software for the label printer is described in this manual.

Label printer and accessories can also be purchased from our company.

We have no experience with other printers and therefore cannot provide support.

Contents

1.	Installation of the SPECTRO-T-3-DOCAL-Scope software.....	3
2.	Operation of the SPECTRO-T-3-DOCAL-Scope software.....	4
2.1	Tab CONNECT	5
2.2	Tab PARA1, PARA2, button SEND, GET, GO, STOP.....	7
2.3	Tab TEACH (teach table).....	10
2.4	Graphical display elements	13
2.5	Tab CALIB.....	18
2.6	Tab DOCU	19
3.	Commissioning the label printer EOS2/300.....	21
3.1	Loading the roll adhesive label and the thermal transfer ribbon.....	22
3.1.1	Loading media from roll.....	22
3.1.2	Loading transfer ribbon.....	24
3.2	Installing the printer driver for Windows via USB cable	25
3.3	Setting the printer properties.....	28

Shortcuts:

SEND	F9
GET	F10
GO	F11
STOP	F12

1. Installation of the SPECTRO-T-3-DOCAL-Scope software

The following requirements must be fulfilled for successful installation of the software:

- Microsoft® Windows® 10
- IBM PC AT or compatible
- VGA graphics
- Microsoft-compatible mouse
- Serial RS232 interface at the PC or USB slot or RJ45 connector
- Cable **cab-las4/PC** for the RS232 interface or **cab-4/USB** USB converter or **cab-4/ETH** Ethernet converter

Please install the software as described below:


1. You can download the software via a provided download link or, if applicable, install it via the provided software DVD. To install the software, start the 'SETUP' program in the 'SOFTWARE' folder.
2. The installation program displays a dialog and suggests to install the software in the C:\"FILENAME" directory on the hard disk. You may accept this suggestion with OK or [ENTER], or you may change the path as desired. Installation is then performed automatically.
3. During the installation process a new program group for the software is created in the Windows Program Manager. In the program group an icon for starting the software is created automatically. When installation is successfully completed the installation program displays "Setup OK".
4. After successful installation the software can be started with a left mouse button double-click on the icon.

Windows™ is a registered trademark of Microsoft Corp.
VGA™ is a trademark of International Business Machines Corp.

2. Operation of the SPECTRO-T-3-DOCAL-Scope software

Please read this chapter first before you start calibration.

When the SPECTRO-T-3-DOCAL-Scope software is started, the following window appears on the Windows interface:



The window size and position will be the same as when the software was last closed. A double-click with the right mouse button, e.g. under the minimise symbol places the window centrally in its original size.

If a connection is not established automatically, e.g. if no sensor is connected, the software can be run in OFFLINE mode. In offline mode it only is possible to exchange parameters with a file on a storage medium, which often is helpful for the purpose of analysing parameter files.

If a sensor is connected and a connection still cannot be established, either the SCOPE version (program at the PC) and the firmware version (program in the sensor) do not match, or the interface to the sensor must be correctly configured.


If different Scope and firmware versions should be the problem, please get the Scope version that matches the firmware from your supplier.

The interface configuration is described in the CONNECT tab chapter.

Pressing the right mouse button on an individual element will call up a short help text.

Due to a better overview, parameters that are not required, displays, graphs, etc., are greyed out or invisible depending on the parameterization.

2.1 Tab CONNECT



CONNECT:

Pressing the **CONNECT** tab opens a window for selecting and configuring the interface.

The **COMMUNICATION PROTOCOL** function field is used for selecting either an **RS232** or a **TCP/IP** protocol.

If **RS232** is selected, a port from 1 to 256 can be selected with **SELECT COM PORT**, depending on which port the sensor is connected to. The sensor operates with a set baudrate that can be modified with **CHANGE BAUDRATE** (see below). The sensor and the user interface both must operate with the same baudrate.

At the user interface the baudrate is set with **SELECT BAUDRATE**. If after starting the software should not automatically establish a connection, the correct baudrate can be found with **SELECT BAUDRATE**.

If an converter is used, the **COM PORT** number can be determined by way of the hardware manager in the system control panel.

A click on the magnifier symbol opens a list with all the possible COM ports in the display.

An RS232 to Ethernet converter (**cab-4/ETH**) is needed if the sensor should communicate through a local network. With this converter a connection to the sensor can be established using the **TCP/IP** protocol.

Parameterisation of the **cab-4/ETH** converter (assigning of IP address, baudrate setting, ...) can be done with the **SensorFinder software** that is available free of charge on the internet.


In order to establish a connection to the converter, its IP address or HOST name must be entered in the field **IP ADDRESS (xxx.xxx.xxx.xxx) OR HOST NAME**. The DROP DOWN menu (down arrow) shows the last 10 IP addresses that were used. An address from this list can be directly selected by clicking on the respective item. The DROP DOWN list is saved and is thus always available when the software is closed.


The **PORT NUMBER** for the **cab-4/ETH** is 5000. This port number must not be changed.

When you press the **TRY TO CONNECT** button, the software tries to establish a connection with the set parameters. The communication status is shown in the display field. If the sensor answers with its FIRMWARE ID, the set connection type can be accepted by pressing **ACCEPT SETTINGS**. You will then be returned to the **PARA** tab. If you get a **TIMEOUT** message, the software could not establish a connection to the sensor. In this case please check if the interface cable is correctly connected, if the sensor is supplied with power, and if the set parameters are correct. If a connection has been accepted by pressing **ACCEPT SETTINGS**, the software starts automatically with these settings when called the next time.

DISCONNECT disconnects the connection between sensor and PC. The software then switches to OFFLINE mode, where it is only possible to exchange parameters with a file on a storage medium.


Under **PANEL ID** a name can be entered that will be displayed at different points in the program window, and that will be recorded in different files (e.g. Record File) as well. With the input field **LANGUAGE** a language can be set with which the individual controls are displayed on the surface. This also applies to the help function that is actuated with the right mouse button.

<p>Please note:</p>  <p>ATTENTION !</p>	<p>The stable function of the interface is a basic prerequisite for measured value transfer from the PC to the sensor.</p> <p>Due to the limited data transfer rate through the serial RS232 interface only slow changes of the raw signals at the sensor front end can be observed in the graphic output window of the PC.</p> <p>For maintaining maximum switching frequency at the sensor data communication with the PC must be stopped (press the STOP button).</p>
--	--




The baudrate for data transfer through the RS232 interface can be set by means of the **SELECT BAUDRATE** drop down menu and **CHANGE BAUDRATE** function field.

If the baudrate should be changed, a connection must first be established by clicking on **TRY TO CONNECT**. The **CHANGE BAUDRATE** button will then be active.




Now a new baudrate can be selected under **SELECT BAUDRATE**.

A click on **CHANGE BAUDRATE** sends the new baudrate information to the sensor.




When the new baudrate information has been successfully sent, the sensor operates with the new baudrate. A window will pop up, prompting you to select **EEPROM** and then to press **SEND**. After a hardware reset the new baudrate only will be used when **EEPROM** and **SEND** have been pressed.

A click on **ACCEPT SETTINGS** saves the current interface settings, which will then be automatically set when the software is restarted.



A click on the **GEN. HW INFO FILE** generates a file in which all the important sensor data are stored in encrypted form. This file can be sent to the manufacturer for diagnostic purposes.

2.2 Tab PARA1, PARA2, button SEND, GET, GO, STOP



PARA1 and PARA2:

A click on **PARA1** or **PARA2** opens a window where the sensor parameters are displayed.

Some parameters are active and can be changed if, for example, vectors are taught after calibration. Others are grayed out and cannot be changed because they were preset during calibration, for example.

The meanings of the parameters are explained in the manual of the sensor.

A right-click on an active parameter (i.e. not grayed out) opens a window with brief information.

SEND [F9]:

By clicking the **SEND** button (or by shortcut key F9) all currently set parameters are transferred between PC and the sensor. The target of the respective parameter transfer is determined by the selected radio button (**RAM**, **EEPROM** or **FILE**).

GET [F10]:

The currently set values can be interrogated from the sensor by clicking on the **GET** button (or with shortcut key button F10). The source of data exchange is determined by the selected button (**RAM**, **EEPROM**, or **FILE**).

RAM:

The current parameters are read from the **RAM** of the sensor on pressing **GET**.

EEPROM:

The current parameters are read from its **EEPROM** upon pressing **GET**.

FILE:


After pressing **SEND**, the current parameters can be written to a selectable file on the hard disk. With **GET** parameters can be read from such a file. When the **SEND** or **GET** button is pressed, a dialog box opens for selecting the desired file.

GO [F11]:

Upon clicking this button, the data transfer from the sensor to the PC is started. The data are displayed in the display elements on the PC interface.

STOP [F12]:

Clicking this button ends the data transfer from the sensor to the PC.



AVERAGE

AVERAGE:

This function field is used for adjusting the number of scanning values (measurement values) over which the raw signal measured at the receiver is averaged. A higher **AVERAGE** default value reduces noise of the raw signals at the receiver unit and there will be a decrease of the maximal available switching frequency of the sensor.

DIGITAL OUTMODE

DIGITAL OUTMODE:

This group of buttons offers the method of how to control the 5 digital outputs.

OFF:

No digital signal is output. All the corresponding function fields are hidden.

DIRECT:

In this mode a maximum of 5 teach vectors or 5 vector groups is permitted.

If in this row-by-row comparison the current space coordinates correspond with the teach-in parameters entered in the vector table, this "hit" in the vector table is displayed as a vector number (V-No.) and is sent **direct** to the digital outputs.

DIRECT HI:

If **DIRECT HI** is activated, the respective digital output is set to HIGH. If no vector is detected, the digital outputs are in the LOW state.

DIRECT LO:

If **DIRECT LO** is activated, the specially digital output is set to LOW, while the other ones are set to HIGH. If no vector is detected, the digital outputs are in the HIGH state.

BINARY HI:

If in the row-by-row comparison the current space coordinates correspond with the teach-parameters entered in the vector table, this "hit" in the vector table is displayed as a vector number (V-No.) and is provided at the digital outputs as a **bit pattern**.

In this mode a maximum of 31 teach vectors or 31 vector groups is permitted.

BINARY LO:

Same function as **BINARY HI**, but the **bit pattern** is output inversely.

VECTOR GROUPS			SELECT HOLD [ms] FOR EACH ROW		
ON					
0	0		255	10	
1	0		0	10	
2	1		1	10	
3	1		2	10	
4	4		3	10	
5	0		4	10	
6	0		5	10	
7	0		6	10	
8	0		7	10	
9	0		8	10	
10	0		9	10	
11	0		10	10	
12	0		11	10	
13	0		12	10	
14	0		13	10	
15	0		14	10	
16	0		15	10	

RESET

RESET 10

V-No:

3

GRP

1

PARA2:

A click on **PARA2** opens a window where vectors in the **TEACH TABLE** can be assigned to certain groups, and for each vector and the error status an explicit **HOLD** time can be set.

Please note:

The sensor must be informed about the vector groups and HOLD settings by pressing SEND.

VECTOR GROUPS:

By means of the **GROUP** table individual rows can be assigned to a group.

In this example, **VECTOR GROUPS** has been set to **ON**, i.e. group evaluation is activated.

Rows 0 and 1 have been assigned to group 0.

Rows 2 and 3 have been assigned to group 1, and row 4 to group 2.

A **GRP** display is shown under the **V-No:** display.

If, as in this example, row 3 is detected in the evaluation, this row and the corresponding group will be visualised.

The group number will be output through the outputs.

A total number of 48 different vectors can be taught.

In evaluation mode **DIRECT HI** and **DIRECT LO** a maximum of 5 groups can be formed (group 0 to 4).

In evaluation mode **BINARY HI** and **BINARY LO** 31 groups can be formed.

All the cell values can be set to 0 by pressing **RESET**.

A double-click on the **GRP** display opens a larger display window.

HOLD in milliseconds [ms]:

The sensor operates with minimum scanning times in the magnitude of less than 100µs. This is why most of the PLCs that are connected to the digital outputs have difficulties with the safe detection of the resulting short switching state changes. Entering values in the table provides pulse lengthening at the digital outputs of the sensor system up to 100 ms. Each individual row can be assigned its own **HOLD** time.

When the **RESET** button is pressed, the complete table is set to the reset value indicated beside the **RESET** button.

Example:

Print marks are transported at a very high speed. The print marks are positioned in the sensor's range only for a very short time (milliseconds or even shorter). A minimum pulse of 10 ms is required for the reliable detection of a mark.


The background is taught to row 0, and the print mark to row 1. This is desirable because it allows the use of the **BEST HIT** evaluation mode.

If row 0 and row 1 overlap seamlessly, the sensor operates perfectly. The output is immediately activated and remains active at least for the time specified in the corresponding row.

If row 0 and row 1 do not overlap, the sensor detects an error at the transition from row 0 to row 1 (print mark), which immediately is sent to the output and remains active there at least for the **HOLD** time. An error inevitably would occur here if **HOLD** for the error state (255) was chosen too high, because the sensor only outputs a status change again after **HOLD** has elapsed (this may be the print mark, but it does not have to be).

It is absolutely necessary here to select a **HOLD** time of 0 for error state 255.

2.3 Tab TEACH (teach table)



TEACH:

Clicking **TEACH** opens a view in which the **TEACH TABLE** and some parameters required for operation of the digital outputs are displayed.


Some parameters are active and can be changed, e.g. if vectors are taught after calibration. Others are grayed out and cannot be changed because they were preset during calibration, for example.

A right-click on an active parameter (i.e. not grayed out) opens a window with brief information.

The **TEACH TABLE** is organised in rows, i.e. the individual parameters for the teach vectors are listed side by side in the respective row.

The sensor can work with up to 48 teach vectors. The number of the respective teach vector is shown in the left column of the table.

Only rows with a green number are used for evaluation by the sensor. The number of rows to be used is defined with **MAXVEC-No.**



After pressing **TEACH DATA TO**, the currently displayed space coordinates and the brightness value are transferred to the line of the **TEACH TABLE** selected under **No.:**. In addition, a tolerance

(**delta E**) is set. The tolerances, as well as the teach values, can be changed if necessary by double-clicking the respective field with the left mouse button (or by pressing F2) by entering numerical values with the PC keyboard.

If **Inc** is activated and the **TEACH DATA TO** button is pressed, an automatic incrementation (increase) of the input field **No.:** by 1 is performed, i.e. the next line in the **TEACH TABLE** is selected.

Pressing the **RESET** button resets the **TEACH TABLE** (RESET value = 0).

TEACH REFERENCE FROM FILE TO ROW 0
00001 NIR PLATE 1

```

*Teach Reference File.ini - Editor
Datei Bearbeiten Format Ansicht Hilfe
[GENERAL INFO]
FILE TYPE: = "TEACH REFERENCE FILE"

[00001]
PLATE NAME = "NIR PLATE 1"
N* = 91.91
i* = -0.27
r* = 0.52
CELL 3 = 0.3
CELL 4 = 0.4
CELL 5 = 0.5

[00002]
PLATE NAME = "NIR PLATE 2"
N* = 56.28
i* = -7.57
r* = -19.69
CELL 3 = 3
CELL 4 = 4
CELL 5 = 5

[00003]
PLATE NAME = "NIR PLATE 3"
N* = 84.59
i* = -1.09
r* = 5.54
CELL 3 = 3.3
CELL 4 = 4.4
CELL 5 = 5.5

Zeile 20, 100% Windows (CRLF) UTF-8
    
```

With **TEACH REFERENCE FROM FILE TO ROW 0** a "teach vector" can be taught from a file into row 0 of the teach table. As soon as you have pressed the button, you will be asked to enter the serial number **of the sample to be taught**. After entering the serial number, you will be asked to select the corresponding "**Teach Reference File.ini**". If the reference (teach vector) is found in the selected file, it is entered in the teach table and shown in the display below the button.

The file with the different teach vectors (reference values) must be created by the user beforehand. It must be structured exactly as described [here](#).

ATTENTION! Some special characters may not be displayed correctly. This varies from country to country. It is therefore recommended to avoid using special characters.

First start the Microsoft Editor, for example, and enter the following text in the first two lines:

```
[GENERAL INFO]
FILE TYPE: = "TEACH REFERENCE FILE"
```

Then enter different reference values (teach vectors) exactly as described here.

In the square brackets is the serial number of the teach vector. **[xxxxxx]**

A name for the teach vector is entered between the quotation marks.

PLATE NAME = "name"

This is followed by the $N \cdot i \cdot r$ values and in CELL3, 4 and 5 the respective tolerances, which are dependent on the SHAPE MODE parameter. These must be entered with a point (not a comma) as separator.

$N^* = 91.91$

$i^* = -0.27$

$r^* = 0.52$

CELL 3 = 0.3 (a*Tol at BLOCK, a*b*Tol at CYLINDER, deltaE at SPHERE)

CELL 4 = 0.4 (b*Tol at BLOCK, L*Tol at CYLINDER, 0 at SPHERE)

CELL 5 = 0.5 (L*Tol at BLOCK, 0 at CYLINDER, 0 at SPHERE)

Any number of teach vectors can be entered in the file.

When all the teach vectors have been entered, select under **File "Save as..."** a suitable **name** for the file with the extension **.ini** and save it, e.g. **Teach Reference File Granules XY.ini**

The file can be opened with the editor at any time in order to change or extend it.

MAXVEC-No.

MAXVEC-No.:

This function field serves for setting the number of vectors to be checked.

With **OUTMODE = BINARY HI** or **BINARY LO** a maximum of 31 vectors or vector groups can be taught.

With **OUTMODE = DIRECT HI** or **DIRECT LO** a maximum of 5 vectors or vector groups can be taught.

If **VECTOR GROUPS = ON**, the sensor can be taught up to 48 vectors.

However, only 31 groups can be formed with **OUTMODE = BINARY** and 5 groups with **DIRECT HI** or **LO**. In the **TEACH TABLE** rows 31-47 therefore have gray background.

The numerical value that is set here determines the current possible scan rate of the sensor. If the number of vectors to be checked is lower, the sensor operates faster. The numerical value that is defined here refers to the number of rows (starting with row 0) in the **TEACH TABLE** (→ TEACH TABLE tab).

SHAPE MODE


SHAPE MODE:

This function field is used to specify whether the space coordinates N^* i^* r^* should be viewed as a block, cylinder, or sphere in space.

When viewed as a block, each space coordinate has its own tolerance (N^*Tol , i^*Tol , r^*Tol).

The space distance **delta E** is calculated from the coordinates i^* and r^* .


A vector is recognised if the current space coordinates lie in the block.



When viewed as a cylinder, the space coordinates i^* and r^* have their own tolerance (i^*r^*Tol), and the space coordinate N^* has its own tolerance (N^*Tol).

The space distance **delta E** is calculated from the coordinates i^* and r^* .


A vector is recognised if the current space coordinates lie in the cylinder.



In sphere mode there only is one tolerance for the space coordinates.

The space distance **delta E** is calculated from the space coordinates N^* i^* r^* .

A vector is recognised if the current space coordinates lie in the sphere.




2.4 Graphical display elements

Tab **XYZ**:

Display of the current raw signals (tristimulus values) **X**, **Y**, **Z** of the 3-fold receiver.

The LED **SAT** indicates if one of the channels is in saturation. In this case, it lights up red.



A double click with the left mouse button in the XYZ graph starts an automatic zoom function. A single click terminates this function.



Tab C SPACE:

Space coordinates of the space selected under **C SPACE** are shown in the displays.

In **GO** mode, the deltas **dN***, **di***, **dr*** are calculated from the hit detected in the sensor and the current space coordinates. (Left graphic)

If the **DOCU** tab is selected and the recording of data via **CAPTURE DATA FRAME** is activated, the deltas are always calculated from the currently applied space coordinates and the teach vector in row 0 in the teach table. If the deltas exceed the taught tolerance, the displays for the space coordinates will be colored orange and the displays for the deltas will be colored according to their space shift. (Right graphic)


Example: The teach value for **N*** in the table is **91** and the tolerance is **2**. The current value of **N*** is **93.94**. It is therefore **2.94** greater than the taught value of **91** and has exceeded the tolerance of **2**. This in turn means that the current surface is brighter than the taught one. In this case, the display **dN*** is shown white. If the **N*** value of the current surface were smaller than the taught-in value of **91** minus **2** tolerance (**89**), then the current surface would be darker and the display **dN*** would be colored black.



Tab C SPACE 3D:

Three-side view of the taught vector in space.

The space coordinates of all taught vectors with their tolerances, and the current space coordinates position are displayed. A three-side view in space was chosen to provide a clearer representation.



A left double-click in one of the graphs causes all the circles to be displayed in grey, only the circle with the detected vector is displayed in color.

A single left click returns to the standard view.

A left double-click in the XYZ graph starts an automatic zoom function.

A single left click closes this zoom function again.

The graph with the color chart in the background can be zoomed in and out.

Tab DOCU:


If the DOCU tab is selected and the recording of data via **CAPTURE DATA FRAME** is activated, the deltas are always calculated from the currently applied space coordinates and the learning vector in line 0 in the teach value table and shown in the individual displays.


If the deltas exceed the taught tolerance, then the corresponding graphs are highlighted in orange.

With the grey arrow keys to the left of the graphs you can scale the Y-axis of the graph.


Use the **RESET** button to set the graph to 0.

Use the green arrow keys in the upper left corner to drag and drop this view over the entire panel.





These numerical value display shows the space coordinates that are calculated from **X, Y, Z**. Calculation is performed as described in **CTRL SPACE**.



These numeric value display shows the deviations of the individual space coordinates of the current surface to the "hit" (**V-No.:**) in the **TEACH TABLE**. The values are calculated on the PC user interface and not in the sensor and are only shown in these displays.



delta E:

This display shows the space distance from a vector hit. Calculation is performed as described in **CTRL SPACE**.

In **FIRST HIT** evaluation mode **delta E** is equal to the distance from a vector hit. If there was no vector hit, **delta E** is calculated in relation to the last valid vector in the vector table (depending on **MAXVEC-No.**)

In **BEST HIT** evaluation mode **delta E** also is equal to the distance from a vector hit. However, if there was no vector hit, **delta E** has the value -1.00.

This also applies if the current intensity $(X+Y+Z)/3$ falls below the **INTLIM** parameter.



V-No.:

This numerical value output field shows the currently detected vector number according to the entry in the **TEACH TABLE**. The currently detected vector number is sent to the digital outputs as a corresponding bit pattern.

A value of 255 means that none of the taught vectors was detected.

A double-click on the display will open a larger display window.



GRP:

The currently detected group **GRP** and not **V-No.:** is applied at the digital outputs as the corresponding bit pattern.

A value of 255 means that none of the vectors or groups that have been learned has been detected.




INO:

This LED display visualises the status of input IN0.

If 0 V is applied at the input, the LED is black.

If 24 V is applied at the input, the LED is green.

This display only is visible if the input is used.



TEMP:

This display shows the temperature in the sensor housing.

The display does **NOT** show degrees Celsius or Fahrenheit.


Please note: The above-mentioned output fields are only updated when data transfer between PC and sensor is active (GO button pressed).

2.5 Tab CALIB

The sensors are factory calibrated. If the **CALIB** parameter is set to **FCAL (Factory CALibration)**, the sensor operates with this factory calibration.

As an alternative the user can himself calibrate the sensor to different surfaces (**User CALibration**). If **CALIB=UCAL** is selected, the sensor operates with the calibration made by the user.

A click on **CALIB** will open the following window:



With **START CALIBRATION ASSISTANT** you can start an assistant that guides you through the calibration.

The calibration can optionally be done with NIR plates whose $N^*i^*r^*$ values are available in a file. During the calibration you will be asked to load this file. Then a NIR plate is placed in front of the sensor. The corresponding $N^*i^*r^*$ values are then loaded from the file by entering the corresponding serial number.

There are 3 preconditions

1. You need **one** reference plate. This is available from the supplier of the sensor.
2. You need different NIR plates. These are available from the supplier of the sensor.
3. You need a file (.ini file) in which the $N^*i^*r^*$ values for the various NIR plates are stored. This file is also available from the supplier (via download → NIR plate Data Files).

Another method is to enter the $N^*i^*r^*$ values manually. In this case you also need a reference surface and different surfaces from which the $N^*i^*r^*$ values are known.

ATTENTION! It may happen that the X_n, Y_n, Z_n values cannot be determined due to an unsuitable choice of reference surface. In this case, try another reference surface or one of the recommended NIR plates.

If the calibration values are saved to a file after successful calibration, they can be loaded as a calibration template for the next calibration, expanded, or sent directly to the sensor.

Upon pressing **GET CF**, the calibration factors that have been determined are displayed in the tab **SENSOR DATA**.

The individual tables, displays and display boxes for calculating the calibration factors are updated automatically during the calibration process. They cannot be changed and need not be paid any further attention.

2.6 Tab DOCU

Clicking **DOCU** opens a view in which, after pressing **CAPTURE DATA FRAME**, a recording of the space coordinates starts depending on the setting in CAPTURE DATA MODE.

If **CAPTURE DATA MODE = MANUAL**, a single frame is picked and displayed.


In case of **CAPTURE DATA MODE = PERIOD**, space coordinates are sampled via a **PERIOD LENGTH [s]** long time, summed up and then averaged and displayed.

With **CAPTURE DATA MODE = WHILE IN0 IS HIGH**, space coordinates frames are recorded and summed up as long as the input **IN0** is set. After **IN0** drops, the average values are formed and displayed.

ATTENTION! This mode only operates if one of the trigger modes is activated in the sensor.

The delta values of the individual space coordinates are calculated from the recorded space coordinates and the teach vector in line 0 in the teach table and displayed in the individual displays.

If the deltas leave the taught tolerance, the corresponding graphs are highlighted in red.



With the button **SELECT RECORD FILE** you select a file in which the **X, Y, Z** values, the space coordinates, the respective **delta** values as well as the hit (**V-No:**) and the sensor temperature can be stored.

If the checkbox **ADD PRINTOUT LIN1 TO RECORDER FILE (COMMENT)** is selected, additionally the content of **PRINTOUT LINE1** is stored in the file.

The file is saved after pressing **CAPTURE DATA FRAME**.

It should be noted that the file is only regenerated after pressing **SELECT RECORD FILE**.

In any other case, the data is simply appended to the file displayed in the file path.

Even if the software has been restarted.

Pressing **PRINT DOCUMENTATION DATA** will output the current space coordinates, their **delta** values and the two text lines **PRINTOUT LINE1** and **PRINTOUT LINE2** to a printer. The button **FILL LINE2 WITH DATE** is used to enter the current date and time into **PRINTOUT LINE2**.

The data can also be output to a label printer. Please note that the labels must be at least 50mm in width and 30mm in height.


If the labels are not output correctly, this can be optimized in the settings of the respective printer(printer-dependent).

After pressing **VIEW RECORD FILE**, a window is opened in which you can display the data from a recorded data file by pressing **LOAD RECORD DATA FILE**.

The data saved in the file are shown in the displays and in the graphs.
 From the entire file only a section of 100 values is shown in the graph.
 However, you can scroll through the entire file using the **BEGIN AT POS** slider.
 The yellow **TIME WINDOW** displays show the time window that the graphs are currently visualizing.

The cursor can be used to move to individual points, the value of which is shown in the displays to the right.
 Moreover, the **TIME AT CURSOR** display shows when this point was recorded.

Press <<< to return to the main window.



3. Commissioning the label printer EOS2/300

We recommend the following label printer and accessories:

Printer	Accessories	Accessories
Company: cab Produkttechnik GmbH & Co. KG Model: cab EOS2/300 Item No. 5978202	Adhesive roll label Item No. 5780036 Material: TF Satin White Width x Height: 50x30mm	Thermal transfer ribbon Item No. 5556661

You can download drivers, documentation, additional software, etc. at the following link:
https://www.cab.de/en/marketing/label-printer/eos25/?ref=nav_lang

The installation of the software for the label printer is described in this manual.

Label printer and accessories can also be purchased from our company.

We have no experience with other printers and therefore cannot provide support.






3.1 Loading the roll adhesive label and the thermal transfer ribbon

See also Operator's Manual EOS2 / EOS5, subitem **Loading Material** (▷ 4 on page 12).

<https://www.cab.de/en/marketing/label-printer/eos25/#dokumentation> → Documentation → Operation Manuals

3.1.1 Loading media from roll



1. Turn ring (2) at the margin stop (1) counterclockwise, so that the arrow points to the symbol , and thus release the margin stop.
 2. Remove the margin stop (1) from the roll retainer (4).
 3. Load label roll (3) on the roll retainer (4) in such a way that the labels can be inserted into the printhead in the right position. The printing side of the labels must be visible from above.
 4. Re-mount the margin stop (1) onto the roll retainer (4). Push the margin stop (1) to the roll (3) until the roll touches both margin stops and a clear resistance is encountered.
 5. Turn ring (2) clockwise, so that the arrow (10) points to the symbol  and thus fix the margin stop (1) on the roll retainer (4).
 6. Turn lever (8) counterclockwise to open printhead.
 7. Position guides (5) by turning the knob (7) so that they are several millimeters wider than the material.
 8. Position material below the roller (6) and guide it through the print unit.
- Attention! Guide material through the print unit below the label sensor (9).**
9. Move guides (5) closely to the edges of the material without clamping the material.
 10. Adjust label sensor (see next page)
 11. Press printhead retainer down and turn lever (8) clockwise to lock the printhead.

Adjusting the label sensor


Note!

When the printer is delivered the label sensor is positioned in the middle of the paper feed.

Thus, the label sensor must only be adjusted if materials with the following characteristics are used:

- Material with reflex or cut-out marks, which are not in the middle.
- Multi-strip material with an even number of strips.
- Material with irregularly shaped labels.


If the labels recommended by us are used, an adjustment is not necessary.



The sensor position (3) is marked with a yellow LED in the sensor retainer.

1. Open the printhead.
2. Bring knob (3) by pressing it into the setting position (3b).
3. Position the sensor holder (1) by turning the knob (3) so that the sensor (2) can detect the front edge of the label in the direction of paper flow or the reflex or cut-out mark.
4. Bring knob (3) by pressing it into the basic position (3a).

3.1.2 Loading transfer ribbon



1. Clean the printhead before loading the transfer ribbon (see Operator's Manual EOS2, ▷ 6.3 on page 18).
2. Open the printhead.
3. Set guide (1) on the ribbon supply hub to the correct transfer ribbon width (Figure left):
 - Hold the hub and unlock the guide (1) by turning it in direction A..
 - Slide the guide (1) in direction B and adjust the guide to the ribbon width using the scale.
 - Hold the hub and lock the guide (1) by turning it in direction C.
4. Slide transfer ribbon roll (5) onto the ribbon supply hub (3) until it reaches the guide (1) so that the color coating of the ribbon faces downward when being unwound.

Note!


To rewind the ribbon a ribbon core (4) is needed that must be at least equal in width to the supply ribbon. When changing the transfer ribbon use the empty supply ribbon core for winding the next ribbon.

5. Adjust the position of the guide on the take-up hub to the width of the ribbon core (4) and push ribbon core on the take-up hub (2).
6. Guide the transfer ribbon through the printing unit as shown in Figure below.

ATTENTION!

Guide transfer ribbon over the label sensor (6).


7. Secure starting end of transfer ribbon to the transfer ribbon core (4) with adhesive tape. Regard counterclockwise rotation direction of the transfer ribbon take-up hub here.
8. Turn transfer ribbon take-up hub (2) counterclockwise to smooth out the feed path of the transfer ribbon.
9. Close the printhead.




3.2 Installing the printer driver for Windows via USB cable

The following describes how to install the driver for the EOS2 label printer under Windows via the USB interface. See also PDF file „Configuration manual cab Label Printers“ under the following link:
<https://www.cab.de/en/marking/label-printer/eos25/#dokumentation>


1. Make sure that the label printer is switched off.
2. Exit all running programs
3. Connect the printer to the power supply and connect the A-B cable to your computer.
ATTENTION!
 Do not yet switch on the printer!
4. First download the printer driver "cab Windows Driver" to the hard disk of your PC. You can find the driver on the cab homepage under the following link:
<https://www.cab.de/en/marking/label-printer/eos25/#software>
 → Driver → cab Windows Driver → Save file
 The driver is then either in the download folder or in the path you may have selected. Unzip the "cab Windows Driver.zip" file.
5. Now turn on the printer. The Windows installation wizard is started automatically.
6. Start the application „PrnInst“ and follow the instructions on the screen. After successful installation, an icon for the label printer appears in the Windows system folder "Printers".



Confirm with "Next".




Select → Install printer driver.



Select → USB interface.

The USB interface may have to be briefly disconnected and then reconnected.



If the printer was recognized, you can still make printer settings here.
However, this is normally not necessary.
Press → Install.

Druckerinstallations-Assistent

Druckereinstellungen
Bitte wählen Sie vor der Installation Drucker-Optionen aus.

Druckername: CAB EOS2/300

Treiberversion: 5.3.03.7326

Portname: USB001

Wählen Sie die Sprache: Deutsch

Als Windows Standarddrucker verwenden

Verlassen < Zurück Installieren

Druckerinstallations-Assistent

Gerätetreiber wird installiert
Druckerinstallations-Assistent installiert den Gerätetreiber.

Gerätetreiber wird installiert.
CAB EOS2/300

Abbrechen

If the installation was successful, the following window appears.
Now press → Exit.

Druckerinstallations-Assistent

Zusammenfassung
Operation abgeschlossen. Bitte lesen Sie die folgende Zusammenfassung.


Installierte Drucker:
Installation von CAB EOS2/300 (ver. 5.3.3.7326) an Schnittstelle USB001
...erfolgreich.

Anderen Drucker installieren


Verlassen

3.3 Setting the printer properties


After the printer has been installed, it is displayed in the Windows system folder "Printers".




Press → Manage and then → Printer settings.
 For → Size, set 50.00 for Width and 30.00 for Height.
 This is the label size.
 Confirm with → Apply and → OK.



Now start the **SPECTRO-T-3-DOCAL-Scope** and establish the connection to the sensor.
 In the **DOCU** tab, some data records can now be recorded.
 The **PRINTOUT LINE** fields can also be written.



Then press → **PRINT DOCUMENTATION DATA**.
 Select the label printer "**CAB EOS2/300**" and confirm with **OK**.



A successful printout looks like this, for example:

