



1. Gloss measurement on polished slabs

The gloss of polished slabs should be measured. For this purpose a gloss measurement sensor type **RLS-GD-15/60°** will be used. At this, the distance from the sensor to the polished slabs is approximately 15mm. The gloss factor can be properly measured as shown in the screen shots.

